

USSN: 10/067,698  
Group No. 2835  
Examiner: Gerald P. Tolin  
Page 2

IN THE SPECIFICATION

Please add "(a first chassis position)" after "the chassis 300" on page 6, line 1.

Please add "(a second chassis position)" after "the heat sink 400" on page 6, line 7.